


MEZO MZ-15



1x	10x	30x	20x	20x	10x	2x	20x	3x	8x	4x
P	C	D	T	U	G	I	E	S	Z	
3x	8x	20x	50x	1x	4x	4x	1x	8x		
N	A	W	R	M	J	K	L	L	L	

Demontaż
przewodnicy

